

BAILEY



Penrose Touring, Scorrier, Redruth, TR16 5BP
01209 820451 service@penrosetouring.co.uk

PENROSE
TOURING


Caravan Damp Report

Customer


Caravan. Lunar Ariva SGLS000LU61012030



BELOW 16% EXCEPT WHERE SHOWN.



BELOW 16% EXCEPT WHERE SHOWN.



WOOD SOFT UNDER DOOR, ALTHOUGH ALL READINGS BELOW 16% ON THIS SIDE.

Guidance Notes

Readings between 0 – 15% no cause for concern.
Readings between 15 – 20% may require further investigation when compared with the average of all readings taken. Consideration should be given to rechecking the area in three months.
Readings greater than 20% will identify areas needing remedial work there may be early signs of water ingress or evidence of moisture. Again consideration should be given to rechecking the area in three months.
When readings go above 30% structural damage may be occurring and deterioration is inevitable.

Service Engineer :

Chris Mether

Date :

7/10/15.

For your attention the torque settings of your wheel bolts should be rechecked after 30 miles / 50 km and before every journey.